Volume 86 • Nos. 1–6

Key to references: 1.35 = January/February, pg. 35; 2.9 = March/April, pg. 9; etc.

A

ACCELERANTS
Pyrotechnic accelerants used to ignite high-temperature arson fires, 6.67
Unknown accelerant used to ignite warehouse fire, 6.26
ADVERTISING SUPPLEMENTS
Alarm and detection systems, 4.79
Apparatus and rescue products, 5.77
Building construction products, 6.81
Extinguishing systems, 1.75
Hazardous materials storage, 2.87
Protective clothing, 2.87
AEROSOL CONTAINERS
Explosion ignites dwelling fire, 6.28
Flammable contents ignited by open flame, 6.25
AIRCRAFT CRASH FIRES
Cargo plane aborts takeoff, crashes, New York, March, 1991, 6.79
Catastrophic, runway collision, B-737 and twin-turbo prop, California, Feb. 1, 1991, 4.72
Catastrophic, twin-engine plane, Alabama, July 10, 1991, 4.72
Catastrophic, twin-engine plane, Florida, Jan. 17, 1991, 4.72
Catastrophic, twin-engine plane, Texas, Sept. 11, 1991, 4.72
Runway collision, Boeing 737 and Metroliner, California, Feb., 1991, 6.76
Runway collision, jet and cargo van, Georgia, May, 1991, 6.77
AIRPORTS
Aircraft fire on runway, New York, March, 1991, 6.79
Aircraft/van fire on runway, Georgia, May, 1991, 6.77
Catastrophic aircraft fire on runway, California, Feb. 1, 1991, 4.72, 6.76
Tank farm fire, Stapleton Airport, Denver, Colo., Nov. 25, 1991, 1.60
ALABAMA
Catastrophic aircraft fire, July 10, 1991, 4.72
Electric generating plant fire, Nov., 1991, 6.76
ALARM DELAYED
Employee(s) confirmed fire, 4.71, 5.56, 6.74
Employee(s) failed to use manual alarms, 6.29
Employee(s) fought fire, 2.28, 4.25, 6.77, 79
Neighbor refused to call fire department, 4.69
No fire detectors, 1.23, 26
Occupant(s) fought fire, 4.26, 5.25, 67
Plant closed for weekend, 1.23
Remote location, 1.23
Smoke detector not functioning, 6.29
Smoke, motion alarms not set off immediately, 3.32
Weather obscured fire, 1.23
ALARM SYSTEMS
Design of, 4.12
ALARMS
Computer use in, 2.32
ALCOHOL
Factor in group home fire, 1.26
AMERICANS WITH DISABILITIES ACT
Effects on builders, owners, 2.14
APARTMENT BUILDING FIRES
Catastrophic, California, Sept. 7, 1991, 4.69
Catastrophic, Illinois, Dec. 9, 1991, 4.67
Catastrophic, Illinois, March 14, 1991, 4.69
Catastrophic, Michigan, July 31, 1991, 4.68
Catastrophic, New Jersey, Feb. 13, 1991, 4.69
Catastrophic, New York, March 13, 1991, 4.67
Maryland, 1991, 3.34
New Hampshire, 1990, 1.26
New Jersey, 1991, 2.28
AQUEOUS FILM-FORMING FOAM (AFFF)
Concentrate extinguishes aircraft fire, 6.76
ASBESTOS
Emergency response protocols for asbestos abatement site fires, 3.55
Exposure response policy, New York, N. Y., 1.42
Haz-mat contamination, terminal fire, 6.76
ASHES
Careless disposal of, cause of dwelling fire, 1.21
ATTICS
Fire spread into, 2.25, 4.69
Fire spread through, 6.76
Fire started in, 4.70
AUTOMOBILE FIRES
Catastrophic, California, Nov. 29, 1991, 4.73
Texas, 1991, 2.28
AUTOMOBILE REPAIR SHOP FIRES
Catastrophic, Ohio, Nov. 11, 1991, 4.70

B

BAILEY, DAN W.
Profile of, 1.16
BEDDING
Ignited by fireworks, 4.26
Ignited by gasoline in fatal fire, 2.28
See also MATTRESSES
BOARD AND CARE FACILITY FIRES
Catastrophic, Colorado, March 4, 1991, 4.70
BOAT FIRES
Catastrophic, sailboat, California, Nov. 16, 1991, 4.73
See also SHIP FIRES
BRITISH COLUMBIA, CANADA
Manufacturing complex fire, 1991, 2.26
BUILDING CODES
Overview of history and content, 3.42
BUILDING MATERIALS
Effect of European Community product testing standards on U.S. products, 5.45
BUILDING SCENE COLUMNS
Life Safety Code, building security provisions, 5.22
Alarm system design, 4.12
Americans With Disabilities Act affects builders, owners, 2.14
Engineering life safety in high-rise buildings, 1.12
Field modifications to fire doors, 6.12
Performance-based codes, 3.20
BUILDING-UNDER-RENOVATION FIRES
California, 1991, 5.26
BUS FIRES
Illinois, 1991, 4.26

C

CALIFORNIA
Aircraft fire, Feb., 1991, 6.76
Building-under-renovation fire, 1991, 5.26
Catastrophic apartment building fire, Sept. 7, 1991, 4.69
Catastrophic boat fire, Nov. 16, 1991, 4.73
Catastrophic motor vehicle fire, Dec. 25, 1991, 4.73
Catastrophic motor vehicle fire, Nov. 29, 1991, 4.73
Catastrophic runway aircraft collision, fire, Feb. 1, 1991, 4.72
Catastrophic wildland fire, Oct. 20, 1991, 4.72, 6.74
Dwelling fires, 1991, 4.26, 6.28
Fatal high-rise office building fire, May 4, 1988, 5.56
Fatal paint plant explosion, fire, 1991, 4.28
High-rise office building fire, Feb. 15, 1992, 5.56
Office building fire, March, 1991, 6.78
Restaurant fire, 1990, 3.34
Sawmill/manufacturing plant fire, March, 1991, 6.79
School fire, 1991, 6.29
Shed fire, 1991, 6.26
Warehouse/office building fire, 1991, 1.23
CANADA
Hazardous materials response, 1.38
CARBON DIOXIDE
Used to extinguish shipboard fire, 6.48
CARPETS AND RUGS
Ignited by cigarette, catastrophic fire cause, 4.68
Ignited by extension cord, catastrophic fire cause, 4.67
CARSON, MARGARET D.
Profile of, 2.20
CATASTROPHIC FIRES
U.S., 1991, study of, 4.62
CEILINGS
Catastrophic fire ignites ceiling coverings, 4.67
Ceiling tiles ignite, suspended ceiling fails, 6.31
Collapse spreads fire, heat, smoke, 6.76
Fire spread through, 4.25, 5.30, 70
Multiple ceilings hide fire, limit access, 3.31
CHEMICAL PLANT FIRES
Catastrophic, Louisiana, May 1, 1991, 4.70, 6.75
Catastrophic, South Carolina, June 17, 1991, 4.70, 6.80
Texas, March, 1991, 6.75
CHILDREN AND CIGARETTE LIGHTERS
Cause of catastrophic fire, 4.70
Cause of fatal fire, 1.22
CHILDREN AND FIREWORKS
Cause of dwelling fire, 4.26
CHILDREN AND MATCHES
Cause of fatal fire, 5.25
CHILDREN, UNATTENDED
Catastrophic fire victims, 4.70
Fatal fire victims, Iowa, 1.22
CHRISTMAS TREE FIRES
Fatal, Iowa, 1991, 1.22
Michigan, 1991, 6.28
CIGARETTE LIGHTERS See CHILDREN AND CIGARETTE LIGHTERS
CIGARETTES
Careless disposal of, catastrophic dwelling fire cause, 4.68, 69
Careless disposal of, catastrophic rooming house fire cause, 4.67
Careless disposal of, store fire, possible cause, 1.21
Careless use of, apartment fire cause, 3.34
Careless use of, group home fire cause, 1.26
Careless use of, nursing home fire cause, 2.26
CLUB FIRES
Athletic club, Indiana, 1992, 6.31
Nightclub, Texas, 1991, 6.25
CODES AND STANDARDS See NFPA CODES AND STANDARDS
COLLEGE BUILDING FIRES
Mixed-use building, Kansas, June, 1991, 6.78
COLORADO
Catastrophic board-and-care facility fire, March 4, 1991, 4.70
COMMUNICATIONS INDUSTRY
Fire protection for, 2.32
COMPARTMENTATION
Lack of, allowed fire spread in sawmill fire, 6.79
Lack of, factor in warehouse fire, 6.78
COMPUTERS AND RELATED EQUIPMENT
Fire protection for, 2.32
Fire service use of, 2.32
Fuel high-rise office building fire, 5.56
CONCEALED SPACES
Ceiling, factor in flashover, 6.31
Ceiling, fire spread into, 6.78
Contributed to fire spread, 6.79
Fire spread through, 3.31, 6.78
CONNECTICUT
Catastrophic dwelling fire, Feb. 16, 1991, 4.67
Dwelling fire, 1991, 4.26
CONVEYOR BELTS
Mechanical failure causes grain to ignite, 4.28
COOKING-AND-HEATING EQUIPMENT FIRES See HEATING-AND-COOKING EQUIPMENT FIRES
COOLING TOWER FIRES
Rooftop tower of high-rise office building, Massachusetts, 1991, 5.28

D

DENVER, COLO.
Tank farm fire, Nov. 25, 1991, 1.60
DETECTION SYSTEMS
Automatic, did not cover area of fire origin, 5.28
Life safety system installed at Winterthur Museum, 5.63
DETECTORS, HEAT, SATISFACTORY PERFORMANCE, 5.30
DETECTORS, HEAT, UNSATISFACTORY PERFORMANCE, 4.70
DETECTORS, SMOKE
Air sampling detectors, overview of, 3.80
Blocked by interior renovations, delayed detection, 6.26
Testing of, fire prevention week theme, 1992, 5.68
DETECTORS, SMOKE, NOT A FACTOR IN FIRE
Aircraft crash, 6.79
Batteries missing, 4.67, 5.25, 6.28, 68
Batteries missing or dead, 4.68
Explosion, 6.28
Fire spread too fast, 2.28
Improperly installed, 3.34
Removed, 3.34
DETECTORS, SMOKE, SATISFACTORY PERFORMANCE, 1.22, 2.27, 6.28, 26, 29
DETENTION FACILITY FIRES
Catastrophic, Missouri, Sept. 14, 1991, 4.70
DIESEL FUEL
Used as fire starter, ignites fireplace fire, 2.29
DINENNO, PHILIP J.
Profile of, 4.20
DOORS
Inoperable, hamper escape in catastrophic food plant fire, 1.29
Open garage door, fire spread by, 1.21
Open, fire spread by draft caused by, 5.25
Open, fire spread through, 4.67, 69
Wood, fire spread through, 4.67
See also EXITS
DOORS, FIRE
Field modifications of, 6.12
Self-closing, prevent fire spread, 4.27
DRILLING PLATFORM FIRES
Catastrophic, Louisiana, Feb. 15, 1991, 4.71

DRILLING RIG FIRES
Track-mounted, Wisconsin, July 9, 1991, 4.72
DROUGHT
Factor in wildland fires, 1991, 4.72, 6.74, 76
DUCTS, HEATING
Catastrophic fire spread through, 4.68
DUNGAN, KENNETH W.
Profile of, 5.20
DUST
Grain dust, ignited by smoldering grain, 4.28
DWELLING FIRES
California, 1991, 4.26, 6.28
Connecticut, 1991, 4.26
Georgia, 1991, 2.29
Iowa, 1991, 1.22, 4.26
Massachusetts, 1991, 1.21
Michigan, 1991, 6.28
Minnesota, 1991, 2.28
Missouri, 1991, 3.34
New York, 1991, 5.25
Oklahoma, 1991, 6.28
Wyoming, 1991, 5.26
DWELLING FIRES, CATASTROPHIC
Connecticut, Feb. 16, 1991, 4.67
Illinois, Jan. 1, 1991, 4.68
Louisiana, Nov. 16, 1991, 4.68
Montana, Sept. 7, 1991, 4.68
New Jersey, June 11, 1991, 4.69
New Jersey, June 16, 1991, 4.69
New York, April 10, 1991, 4.67
New York, April 21, 1991, 4.69
New York, Dec. 22, 1991, 4.68
New York, Feb. 8, 1991, 4.68
New York, Nov. 22, 1991, 4.68
Ohio, Dec. 15, 1991, 4.69
Oklahoma, Aug. 31, 1991, 4.69
Oklahoma, Feb. 1, 1991, 4.68
Pennsylvania, Dec. 14, 1991, 4.69
Pennsylvania, Feb. 14, 1991, 4.67
Tennessee, March 9, 1991, 4.67
Texas, Oct. 7, 1991, 4.68
Wisconsin, April 22, 1991, 4.68

E

EDITORIALS
A plumber's nightmare, 4.4
Cast a vote for fire safety, 6.4
Connections, 5.4
Fire protection's future, 1.4
High technology's value for fire protection, 2.4
NFPA's new president, George D. Miller, 3.4
EDUCATIONAL OCCUPANCY FIRES
University building, Kansas, June, 1991, 6.78
See also SCHOOL FIRES
EGRESS
Inadequate, factor in fatal fire, 6.77
ELECTRIC GENERATING PLANT FIRES
Alabama, Nov., 1991, 6.76
ELECTRICAL EQUIPMENT FIRES
Air-compressor ignites lubricating oil, 6.79
Coffeepot ignites paper products, 2.25
Electrical cord overheats, ignites carpet, 3.32
Emergency light ignites stored clothing, 2.27
Extension cord, defective, ignites Chrismas tree, 6.28
Extension cord, misused or overloaded, ignites fire, 4.69
Extension cord, overloaded, ignites carpeting, 4.67
Fluorescent light ballast ignites foam insulation, 1.26
Heat tape ignites wood eaves, 1.23
Radio cord ignites cabinet, 6.29
Refrigerator ignites wood paneling, counter top, 6.31
Vacuum cleaner ignites gasoline vapors, 5.28
Waste-handling machine overheats, ignites fiber residue, 5.30
See also HEATING-AND-COOKING EQUIPMENT FIRES
ELECTRICAL FIRES
Electrical arc ignites flammable gas, 6.28
Electrical service circuit protection fails, arcing ignites cable insulation, 6.78
Ground fault arc and explosion ignites fire, 6.78
High-voltage power line arc ignites bus, 4.26
Short circuit arc ignites mine fire, 6.77
Short circuit in battery ignites truck, shed, 6.26
Short circuit in extension cord ignites Christmas tree, 6.28
Short circuit in lighting, sound equipment causes fire, 6.25
Short circuit in wiring ignites paneling, 2.28
Wiring ignites joist, 3.34
Wiring short circuits, ignites wood framing, 4.68
Wiring malfuncts, causes fire, 4.67
ELECTRICAL SAFETY COLUMNS
National Electrical Code prevents hot tub, spa accidents, 4.22
Excessive fault current prevention, 2.80
Fire investigation safety precautions, 3.38
Service-entrance conductors protect against overloads, 1.72
Who interprets the NEC?, 5.12
ELECTRONICS INDUSTRY
Fire protection for, 2.32
EUROPEAN COMMUNITY (EC 1992)
Product testing standards, 5.45
EVACUATIONS
Aircraft, successful, 6.77
Bus, electrically charged, successful, 4.26
Food plant, unsuccessful, 1.29
Nursing home, successful, 4.27, 6.29
Office building, successful, 5.28
School, successful, 2.25, 4.27, 6.29
EXITS
Blocked by burning mattress, factor in fatal fire, 5.25
Blocked by furniture, factor in catastrophic fires, 4.67, 69
Blocked by security bars, factor in fatal fire, 6.28
Locked or blocked, factor in catastrophic fire, 4.70
See also DOORS
EXPLOSIONS AND FIRES
Aerosol container explodes, ignites dwelling, 6.28
Aircraft in flight, Texas, Sept. 11, 1991, 4.72
Black powder manufacturing plant, Pennsylvania, May 15, 1991, 4.71
Boat fire, California, Nov. 16, 1991, 4.73
Chemical plant, Louisiana, May 1, 1991, 4.70, 6.75
Chemical plant, South Carolina, June 17, 1991, 4.70, 6.80
Chemical plant, Texas, March, 1991, 6.75
Fireworks plant, Wisconsin, May 16, 1991, 4.71
Gasoline vapor ignited by gas furnace, dwelling, Michigan, 1991, 6.28
Grain dust at mill and storage facility, Washington, 1991, 4.28
Munitions ship explosion, Halifax, Nova Scotia, Dec. 6, 1917, 3.96
Oil well, Ohio, Oct. 10, 1991, 4.71
Paint plant, California, 1991, 4.28
Petroleum refinery, Louisiana, March 3, 1991, 4.70, 6.77
Refinery, Texas, April, 1991, 6.75
EXPLOSIVES
Improperly stored, catastrophic fire cause, 4.72
EXTINGUISHERS
Ineffective in dairy plant fire, 3.32
EXTINGUISHERS, DRY CHEMICAL
Portable, successful in store fire, 6.25
Successful on deep fat fryer fire, 5.25

F

FIRE BRIGADES, INDUSTRIAL
NFPA 600 requirements, 2.46
FIRE COMMAND COLUMNS
Deploying resources effectively, 6.104
Fire critiques as evidence for lawsuits, 1.18
Matching response capabilities to fire conditions, 4.30
Shrinking budgets, staffing realities, 3.28
Standard operating procedures reduce legal risk, 2.30
Urban violence complicates fire service operations, 5.14
FIRE CRITIQUES
Use of critiques in lawsuits, 1.18
FIRE DEATHS, U. S. See CATASTROPHIC FIRES; FIRE FIGHTER FATALITIES, U.S.
FIRE DOORS See DOORS, FIRE
FIRE FIGHTER FATALITIES
Furniture refinishing plant fire, Dec. 20, 1991, 3.73
High-rise building fires, 5.56
High-rise club/hotel fire, Indianapolis, Ind., Feb. 5, 1992, 6.31
U.S., 1991 report, 4.40
FIRE FIGHTER INJURIES
1991 report, 6.56
FIRE FIGHTER SAFETY
Reconciling safety and customer service needs, 4.86
FIRE LOSS, U.S.
1991 report, 5.32
FIRE PREVENTION WEEK
1992 theme: smoke detectors are lifesavers, 5.68
FIRE PRODUCTS
Fire fighter fatalities related to, 1991, 4.46, 48, 50, 51, 54
Fire fighter injuries related to, 1991, 6.62, 63, 64, 65
FIRE PROTECTION
Future of, NFPA Board of Directors view, 1.47
FIRE PUMP
Failure to operate automatically, 2.25
FIRESAFETY
Health care facilities, fire safety prognosis for '90s, 3.89
See also FIRESAFETY EDUCATION
FIRESAFETY EDUCATION
Preschool program saves lives in dwelling fire, 2.28
FIRE SERVICE ADMINISTRATION
Deploying resources effectively, 6.104
Management reviews, 3.124
Marketing fire service to gain public support, 1.90
Marketing fire service via improved public relations, 1.67
NFPA survey, wildfire managers top concerns, 5.96
Participatory management enhances volunteer morale, 1.96
Shrinking budgets, staffing realities, 3.28
Use of fire critiques in lawsuits, 1.18
FIRE SERVICE APPARATUS AND EQUIPMENT
Development of NFPA standards for, 2.41
Fire fighter fatalities related to, 1991, 4.43, 48, 51, 54
Fire fighter injuries related to, 1991, 6.58, 63, 64
Robot use pioneered in Tokyo, 2.67
FIRE SERVICE OPERATIONS
At asbestos abatement site fires, 3.55
Matching response capabilities to fire conditions, 4.30
Urban violence complicates, 5.14
FIRE SERVICE OPERATIONS HAMPERED
Access limited by cargo shift in aircraft fire, 6.79
Access limited by ceilings, barred/covered windows, 3.31
Access limited by difficult-to-open doors, 6.26
Access limited by flooding, 4.72
Access limited by locked doors, 4.70
Access limited by stored furniture, 4.67
Access limited by stored goods, 6.79
Access limited to roof, ceiling voids, 5.30
Access limited to site, 1.26
Bystanders interfered, 4.70
Electrical power loss, 4.71, 5.56, 6.74, 78
Emergency lighting failed, 6.78
Flashback fires on cargo containers, 6.79
Foam suppression supplies exhausted, 1.60
Hazardous materials present, 3.33
Machinery, hazards posed by operating, 5.30
Outdated fire plans, 6.26
Remote location, 1.23
Rugged terrain, 6.76
Rural location, 4.67
Smoke density, 6.76
Staffing limited, 4.25, 6.78
Structural collapse, 4.71, 6.75
Wall collapse, 6.78
Water pressure inadequate, 4.71, 5.56, 6.74
Water supply disrupted by explosion, 6.75
Water supply inadequate, 2.26, 4.25, 5.30, 6.79, 26
Water supply remote, 6.26
Weather (high temperature), 4.25
Weather (low temperature), 1.26, 6.26, 60
Weather (rain), 4.72
See also DROUGHT
See also WIND
FIRE TESTS
European Community product testing standards effect on U.S. building materials, 5.45
FIREPLACES
Diesel fuel ignites fire, 2.29
FIRESTOPPING
Lack of, factor in firespread, 4.25
FIREWATCH COLUMNS 1.21, 2.25, 3.31, 4.25, 5.25, 6.25
FIREWORKS
Illegal, cause of dwelling fire, 4.26
Illegal, cause of school fire, 4.27
Manufacturing plant explosion and fire, 4.71
Overview of fire losses and injuries caused by fireworks, 4.56
FIRST RESPONSE COLUMNS
Fire service management reviews, 3.124
Improving fire protection despite budget limits, 6.14
Marketing fire service to gain public support, 1.90
NFPA members vote on minimum staffing issue, NFPA 1500, 4.96
Positive image wins budget support, 2.96
FLAMMABLE, COMBUSTIBLE LIQUIDS FIRES
Furniture refinishing liquids ignite combustibles in catastrophic fire, 4.71
Kerosene fuels catastrophic fire, 4.69
Rubbing alcohol used to ignite catastrophic fire, 4.67
Unknown liquid used to ignite catastrophic fire, 4.69
See also GASOLINE, OIL, PROPANE, VAPOR FIRES

FLASHOVERS
Club/hotel fire, Indiana, 1992, 6.31
Rooming house fire, Ohio, Feb. 18, 1991, 4.67
FLOORS
Collapse traps fire fighters, 3.73
FLORIDA
Catastrophic aircraft fire, Florida, Jan. 17, 1991, 4.72
FOAM RUBBER
Ignited in catastrophic fire, 4.67
FOOD PLANT FIRES
Catastrophic, North Carolina, Sept. 3, 1991, 1.29
FOREST FIRES See WILDLAND FIRES
FORKLIFT FIRES
Electric malfunction ignites warehouse fire, 6.75
Spark ignites solvent vapors, 4.28
FURNISHINGS
Factors affecting the fire hazards of, 4.33
Fuel club/hotel fire, 6.31
Furniture blocks windows in catastrophic fire, 4.69
Stored furnishings block access/egress in catastrophic fire, 4.67
FURNITURE, UPHOLSTERED
Chair, ignited by cigarette, 4.67, 68, 69
Sofa, accidentally ignited, 4.69

G

GARAGE, AUTOMOBILE REPAIR, FIRES See AUTOMOBILE REPAIR SHOP FIRES
GARAGE, RESIDENTIAL, FIRES
Catastrophic, Wisconsin, April 22, 1991, 4.68
GAS FIRES
Fire-generated combustible gases cause flashover, fire spread, 6.31
Hydrogen, ignited by LPG burner, 5.28
Isobutyl propane, ignited by electrical arc, 6.28
Liquefied petroleum gas (LPG), burner ignites leaking hydrogen, 5.28
Natural, burners ignite hydraulic oil, 4.70
Natural, ignited by oil fire, 1.29
Natural, ignited by pilot light, 4.68, 6.25
Natural, ignition source unknown, 4.71
Natural, pilot light ignites gasoline vapors, 5.26
Pentane, ignited by hot plate, 3.33
See also HEATING-AND-COOKING EQUIPMENT FIRES
GAS LINES
Propane, failed, fuel catastrophic fire, 4.70
GASOLINE
Used as kerosene heater fuel, ignited bedding, 2.28
Vapors from spilled gasoline ignited by pilot light, 5.26
Vapors ignited by gas furnace, 6.28
Vapors, flammable, ignited by spark from vacuum cleaner, 5.28
See also AUTOMOBILE FIRES, TRUCK FIRES
GEORGIA
Aircraft/truck fire, May, 1991, 6.77
Fatal dwelling fire, 1991, 2.29
GRAIN DUST
Causes explosion at mill and storage facility, Washington, 1991, 4.28
GRASS FIRES
Texas, 1991, 2.28
GREASE FIRES
Ignited on stove in school fire, 6.29
GREENE, OLIN L.
Profile of, 3.26
GREENHOUSE FIRES
Massachusetts, 1991, 4.25
GROUP HOME FIRES
Catastrophic, Texas, March 24, 1991, 4.70
New Hampshire, 1990, 1.26

H

HALIFAX, NOVA SCOTIA
Munitions ship explosion, Dec. 6, 1917, 3.96
HALONS
Extinguish aircraft fire, 6.76
Manually activated system not a factor in fire, 6.79
Museums and other applications, 5.66
HAZ-MAT ISSUES COLUMNS
Isman, Warren, legacy to hazardous materials instruction, 2.22
Lifesaving principles, 3.136
Train responders to have a safe attitude, 6.89
HAZARDOUS MATERIALS
Factor in chemical plant fire, 6.75, 80
Factor in food plant fire, 6.80
Hampered fire fighting, chemical laboratory fire, 3.33
Munition ship explosion, Halifax, Nova Scotia, Dec. 6, 1917, 3.96
Response capabilities, assessment of, 1.36
Sprinklers caused paint vats to overflow, 4.28
See also ASBESTOS, HAZ-MAT ISSUES COLUMN
HEALTH CARE FACILITIES FIRES
Firesafety prognosis for '90s, 3.89
See also HOSPITAL FIRES
See also NURSING HOME FIRES
HEAT DETECTORS See DETECTORS, HEAT
HEATING-AND-COOKING EQUIPMENT FIRES
Deep fat fryer overheats, ignites contents, 5.25
Catastrophic, electric heater ignites combustibles, 4.69
Catastrophic, electric heater ignites mattress, furniture, newspapers, 4.67
Electric heater possible cause of fatal fire, 6.28
Electric hot plate ignites pentane vapors in lab fire, 3.33
Catastrophic, electric hot plate ignites table, 4.68
Gas burner ignites grease, food deposits, 3.34
Gas fryer pilot light ignites leaking natural gas, 6.25
Hydraulic oil ignited by natural gas burners, 1.29
Kerosene heater using gasoline ignites bedding, 2.28
Catastrophic, space heater ignites combustible liquids, 4.71
Catastrophic, space heater ignites combustibles, 4.68
Catastrophic, toaster oven cord ignites wood framing, 4.67
Wood stove, radiant heat from flue ignites stored wood, 5.25
HIGH-RISE BUILDING FIRES
Catastrophic, office building, Pennsylvania, Feb. 23, 1991, 4.71, 5.56, 6.74
Club/hotel, Indianapolis, Ind., Feb. 3, 1992, 6.31
Fire protection needs revealed by recent fires, 5.56
Office building, California, March, 1991, 6.78
Office building, Los Angeles, Calif., Feb. 15, 1992, 5.56
Office building, Los Angeles, Calif., May 4, 1988, 5.56
Office building, Massachusetts, 1991, 5.28
HIGH-RISE BUILDINGS
Life safety codes and standards for, 1.12
HIGH-TECH INDUSTRIES
Fire protection for, 2.32
HOODS, KITCHEN VENTILATION
Blocks sprinklers from deep fat fryer fire, 5.25
Sprinkler in hood extinguishes fire, 6.25
HOSPITAL FIRES
Pennsylvania, 1991, 2.27
Tennessee, 1991, 5.25
HOT TUBS
National Electrical Code prevents accidents, 4.22
HOTEL FIRES
Catastrophic, Minnesota, July 12, 1991, 4.67
Indiana, 1992, 6.31
Michigan, 1991, 1.22
HVAC SYSTEMS
Distributes combustion products in high-rise office building fire, 5.56
Factor in high-rise club/hotel fire, 6.31

I

ILLINOIS
Bus fire, 1991, 4.26
Catastrophic apartment building fire, Dec. 9, 1991, 4.67
Catastrophic apartment building, March 14, 1991, 4.69
Catastrophic dwelling fire, Jan. 1, 1991, 4.68
Coal mine fire, Sept., 1991, 6.77
Restaurant fire, 1991, 5.30
IMPERIAL FOODS PROCESSING PLANT FIRE
Catastrophic, North Carolina, Sept. 3, 1991, 1.29
INCENDIARY (SUSPICIOUS) FIRES
Building under renovation, California, 5.26
Catastrophic, apartment building, California, Sept. 7, 1991, 4.69
Catastrophic, apartment building, New York, March 13, 1991, 4.67
Catastrophic, vacant store, California, Oct. 22, 1991, 4.71
Government building, Massachusetts, 1991, 6.26
Hotel, Michigan, 1991, 1.22
Manufacturing plant, Michigan, Aug., 1991, 6.78
Manufacturing plant, Pennsylvania, June, 1991, 6.80
Multiple-occupancy building, Massachusetts, 1991, 1.23
Nursing home, Utah, 1991, 4.27
Pyrotechnic accelerants used in Washington fires, 6.67
Restaurant, Illinois, 1991, 5.30
School, Nova Scotia, Canada, 1991, 5.30
School, Oregon, 1991, 2.25
Shopping mall, New York, May, 1991, 6.77
Store, Michigan, 1991, 6.25
Warehouse, Missouri, 1991, 6.26
Warehouse/office building, California, 1991, 1.23
Wildland/urban interface, California, Oct., 1991, 6.74
INDIANA
Fatal high-rise club/hotel fire, Feb. 5, 1992, 6.31
INDIANAPOLIS, IND.
Fatal high-rise club/hotel fire, Feb. 5, 1992, 6.31
INSTITUTIONAL OCCUPANCIES See separately listed occupancies
INTERIOR FINISHES
Factors affecting fire hazards of, 4.33
Fuel catastrophic fire, 4.67, 69
Wood paneling fuels club/hotel fire, 6.31
INTOXICATION
Factor in catastrophic fire, 4.68, 69
IOWA
Dwelling fire, 1991, 4.26
Fatal dwelling fire, 1991, 1.22

J

JAPAN
Tokyo fire service pioneers robot use, 2.67
JUVENILE FIRESETTING
Catastrophic apartment building fire cause, 4.67
School fire cause, 5.30
School fire caused by fireworks prank, 4.27

K

KANSAS
College building fire, June, 1991, 6.78

L

LABORATORY FIRES
Michigan, 1991, 3.33
Pennsylvania, 1991, 4.25
Texas, 1991, 5.28
LARGE-LOSS FIRES, U. S.
1991, study of, 6.40
LARGE-LOSS-OF-LIFE FIRES
North Carolina (food plant), Sept. 3, 1991, 1.29
LIFE SAFETY CODE
Building security provisions, 5.22
High-rise buildings, standards for, 1.12
Overview of history and content, 3.42
LIFE SAFETY SYSTEMS
Microprocessor-controlled system at Winterthur Museum, 5.63
LIGHTNING
Cause of school fire, Kansas, June, 1991, 6.78
LOS ANGELES, CALIF.
Fatal high-rise office building fire, May 4, 1988, 5.56
High-rise office building fire, Feb. 15, 1992, 5.56

LOUISIANA
Catastrophic drilling platform fire, Feb. 15, 1991, 4.71
Catastrophic dwelling fire, Nov. 16, 1991, 4.68
Catastrophic manufacturing plant fire, May 1, 1991, 4.70, 6.75
Catastrophic petroleum refinery fire, March 3, 1991, 4.70, 6.77
LP-GAS FIRES
Burner ignites leaking hydrogen, 5.28

M

MANUFACTURED HOME FIRES
Fatal, North Carolina, 1991, 2.28
Overview of fire experience, 3.62
MANUFACTURING PLANT FIRES
Apparel, Michigan, Aug., 1991, 6.78
Black powder, Pennsylvania, May 15, 1991, 4.71
Chemicals, Louisiana, May 1, 1991, 4.70, 6.75
Chemicals, South Carolina, June 17, 1991, 4.70, 6.80
Chemicals, Texas, March, 1991, 6.75
Dairy, South Carolina, 1991, 3.32
Fireworks, Wisconsin, May 16, 1991, 4.71
Food processing, North Carolina, Sept. 3, 1991, 1.29, 4.70
Food processing, Pennsylvania, June, 1991, 6.80
Furniture refinishing, Pennsylvania, Dec. 20, 1991, 3.73, 4.71
Meat packing, Texas, June, 1991, 6.79
Paint, California, 1991, 4.28
Sawmill, Wyoming, 1991, 1.26
Shingles, British Columbia, 2.26
MARINA FIRES
Washington, 1990, 1.26
MARYLAND
Fatal apartment building fire, 1991, 3.34
Store fire, 1991, 3.31
MASSACHUSETTS
Dwelling fire, 1991, 1.21
Government building fire, 1991, 6.26
Greenhouse fire, 1991, 4.25
High-rise office building fire, 1991, 5.28
Multiple-occupancy building fire, 1991, 1.23
School fire, 1991, 4.27
Storage facility fire, 5.28
MATCHES See CHILDREN AND MATCHES
MATTRESSES
Ignited by arcing electric heater, 4.67
Ignited by child, 4.70
Ignited by child with matches, 5.25
Ignited by juvenile with rubbing alcohol, 4.67
MICHIGAN
Catastrophic apartment building fire, July 31, 1991, 4.68
Chemical laboratory fire, 1991, 3.33
Dwelling fire, 1991, 6.28
Fatal dwelling fire, 1991, 6.28
Hotel fire, 1991, 1.22
Manufacturing plant fire, Aug., 1991, 6.78
Store fire, 1991, 6.25
Truck fire, 1991, 6.29
Vacant building fire, 1991, 2.29
MILL FIRES
Fiber mill, North Carolina, 1991, 5.30
Grain mill and storage facility, Washington, 1991, 4.28
Sawmill and manufacturing plant, California, March, 1991, 6.79
MILLER, GEORGE D.
Interview with, 3.40
Selection as NFPA president, 3.4
MINE FIRES
Coal, Illinois, Sept. 1991, 6.77
MINNESOTA
Catastrophic hotel fire, July 12, 1991, 4.67
Dwelling fire, 1991, 2.28
Restaurant fire, 1991, 6.25
MISSOURI
Catastrophic prison fire, Sept. 14, 1991, 4.70
Fatal dwelling fire, 1991, 3.34
Warehouse fire, 1991, 6.26
MONTANA
Catastrophic dwelling fire, Sept. 7, 1991, 4.68
MULTIPLE-OCCUPANCY FIRES
Indiana, 1992, 6.31
Kansas, June, 1991, 6.78
Massachusetts, 1991, 1.23
MUSEUMS
Life safety system for Winterthur, 5.63

N

NATIONAL ELECTRICAL CODE
1993 edition, changes in, 5.50
Hot tub and spa accident prevention, 4.22
Interpreting the code, 5.12
NATURAL GAS See GAS
NEW HAMPSHIRE
Group home fire, 1990, 1.26
Nursing home fire, 1991, 6.29
NEW JERSEY
Catastrophic apartment building fire, Feb. 13, 1991, 4.69
Catastrophic dwelling fire, June 11, 1991, 4.69
Catastrophic dwelling fire, June 16, 1991, 4.69
Fatal apartment building fire, 1991, 2.28
Store fire, 1990, 1.21
Store fire, Jan., 1991, 6.78
NEW ORLEANS, LA.
Fire department profile, 2.61
NEW YORK
Aircraft fire, March, 1991, 6.79
Catastrophic apartment building fire, March 13, 1991, 4.67
Catastrophic dwelling fire, April 10, 1991, 4.67
Catastrophic dwelling fire, April 21, 1991, 4.69
Catastrophic dwelling fire, Dec. 22, 1991, 4.68
Catastrophic dwelling fire, Feb. 8, 1991, 4.68
Catastrophic dwelling fire, Nov. 22, 1991, 4.68
Catastrophic motor vehicle fire, May 20, 1991, 4.72
Fatal dwelling fires, 1991, 5.25
Passenger terminal fire, Sept., 1991, 6.76
Shopping mall fire, May, 1991, 6.77
NEW YORK, N. Y.
Asbestos exposure response policy, 1.42
NFPA
Board of Directors view of future of fire protection, 1.47
Fall meeting, 1992, preview, 5.73
Miller, George D., selected as new president, 3.4
Wildland Fire Management Section survey, 1.74, 2.66, 5.96
NFPA ANNUAL MEETING, NINETY-SIXTH
Highlights of 1992 meeting, 4.74
Preview, 2.49
NFPA CODES AND STANDARDS
Fire apparatus standards, development of, 2.41
Hazardous materials response, 1.45
High-rise buildings, standards for, 1.12
Importance of standards to fire service, 3.36
Model building codes, 3.42
NFPA 101, *Life Safety Code*, 3.42, 5.22
NFPA 1500, *Fire Department Occupational Safety and Health Program*, minimum staffing issue, 4.96
NFPA 600, *Private Fire Brigades*, 2.41
NFPA 70, *National Electrical Code*, 5.12, 50
NFPA 80, *Fire Doors and Windows*, modifications to fire doors under, 6.12
Voting procedures for NFPA consensus standards, 6.4
NIGHT CLUB FIRES
Texas, 1991, 6.25
NORTH CAROLINA
Catastrophic manufacturing plant fire, Sept. 3, 1991, 1.29, 4.70
Fatal manufactured home fire, 1991, 2.28
Mill fire, 1991, 5.30
NOVA SCOTIA, CANADA
Munitions ship explosion, Dec. 6, 1917, 3.96
School fire, 1991, 5.30
NURSING HOME FIRES
Massachusetts, 1991, 2.26
New Hampshire, 1991, 6.29
Utah, 1991, 4.27

O

OCCUPATIONAL SAFETY AND HEALTH ADMINISTRATION (OSHA)
Fire safety review urged, 1.34
OFFICE BUILDING FIRES
California, 1991, 1.23
California, March, 1991, 6.78
Catastrophic, Pennsylvania, Feb. 23, 1991, 4.71, 5.56, 6.74
Los Angeles, Calif., Feb. 15, 1992, 5.56
Los Angeles, Calif., May 4, 1988, 5.56
Massachusetts, 1991, 5.28
Modern office environments increase fire hazards, 5.56
Virginia, 1991, 2.25
OHIO
Catastrophic automobile repair shop fire, Nov. 11, 1991, 4.70
Catastrophic dwelling fire, Dec. 15, 1991, 4.69
Catastrophic oil well fire, Oct. 10, 1991, 4.71
Catastrophic rooming house fire, Feb. 18, 1991, 4.67
OIL
Cooking oil ignites wood deck, 4.26
Cooking oil overheats and ignites, 4.26
Hydraulic oil ignited by natural gas burners, 1.29, 4.70
Hydraulic oil residue factor in fire spread, 3.32
Superheated oil and water cause steam explosion, catastrophic fire, 4.70
OIL WELL FIRES
Catastrophic, Ohio, Oct. 10, 1991, 4.71
OKLAHOMA
Catastrophic dwelling fire, Aug. 31, 1991, 4.69
Catastrophic dwelling fire, Feb. 1, 1991, 4.68
Fatal dwelling fire, 1991, 6.28
OPENINGS
Unprotected openings factor in store fire, 6.78
See also STAIRWAYS
OREGON
School fire, 1991, 2.25
Wildland fire, Oct., 1991, 6.76
OXYGEN
Ignited by smoking in nursing home fire, 2.26
Oxygen-enriched atmosphere fueled aircraft fire, 6.76

P

PAINT MANUFACTURING PLANT FIRES
California, 1991, 4.28
PAPER
Used to ignite government building fire, 6.26
PENNSYLVANIA
Catastrophic dwelling fire, Dec. 14, 1991, 4.69
Catastrophic dwelling fire, Feb. 14, 1991, 4.67
Catastrophic furniture refinishing plant fire, Dec. 20, 1991, 3.73
Catastrophic high-rise office building fire, Feb. 23, 1991, 4.71, 5.56, 6.74
Catastrophic manufacturing plant fire, Dec. 20, 1991, 4.71
Catastrophic manufacturing plant fire, May 15, 1991, 4.71
Hospital fire, 1991, 2.27
Manufacturing plant/warehouse fire, June, 1991, 6.80
Research laboratory fire, 1991, 4.25
Warehouse fire, 1991, 2.27
PHILADELPHIA, PA.
High-rise office building fire, Feb. 23, 1991, 5.56
PLASTICS FIRES
Trash container, lined with plastic bag, ignited by cigarettes, 4.69
POWER SAW
Gasoline-powered saw ignites roof fire, 3.31
PRISON FIRES See DETENTION FACILITY FIRES
PROFILE COLUMNS
Bailey, Dan W., 1.16
Carson, Margaret D., 2.20
DiNenno, Philip J., 4.20
Dungan, Kenneth W., 5.20
Greene, Olin L., 3.26
Smittle, Walter, III, 6.20
PROPANE
Gas lines fail, fuel catastrophic fire, 4.70
Isobutyl propane, ignited by electrical arc, 6.28
LPG burner ignites hydrogen, 5.28
PUBLIC ASSEMBLY FIRES
Visitors center, Utah, 1991, 1.23

R

RECREATIONAL VEHICLE FIRES
Camper van, catastrophic, Ohio, Nov. 11. 1991, 4.70
Jet ski, vacuum cleaner ignites gasoline vapors, 5.28
REFINERIES, OIL, FIRES
Louisiana, March 3, 1991, 4.70, 6.77
Texas, April, 1991, 6.75
RESEARCH LABORATORY FIRES
Pennsylvania, 1991, 4.25
RESIDENTIAL FIRES See APARTMENT BUILDING FIRES; DWELLING FIRES

RESTAURANT FIRES
California, 1990, 3.34
Illinois, 1991, 5.30
Minnesota, 1991, 6.25
ROBOTS
Tokyo fire service pioneers use, 2.67
ROOFS
Collapse in manufacturing plant fire, 6.80
Collapse in store fire, 6.78
Fire spread through, 5.30
Fire spread through fiberglass van roof, 4.70
Fire spread to, 4.69, 70
Ignited by fireworks, 4.27
Ignited by gasoline-powered saw, 3.31
Ignited by lightning, framing collapses, 6.78
See also WOOD SHINGLES, SHAKES
ROOMING HOUSE FIRES
Catastrophic, Ohio, Feb. 18, 1991, 4.67
RUBBISH AND TRASH
Ignited by cigarettes in catastrophic fire, 4.69
Ignited by unknown source in catastrophic fire, 4.69

S

SAWMILL FIRES
California, March, 1991, 6.79
Wyoming, 1991, 1.26
SCHOOL FIRES
California, 1991, 6.29
Elementary, Oregon, 1991, 2.25
Secondary, Massachusetts, 1991, 4.27
Unoccupied, Nova Scotia, Canada, 1991, 5.30
SEATTLE, WASH.
Ship fire, Sept. 16, 1991, 6.48
SECURITY PROVISIONS
Electronic locking devices hindered rescue in catastrophic prison fire, 4.70
Locked doors factor in catastrophic manufacturing plant fire, 4.70
SEMICONDUCTOR MANUFACTURING
Fire protection for, 2.32
SHED FIRES
California, 1991, 6.26
Catastrophic, Missouri, Sept. 14, 1991, 4.70
SHIP EXPLOSIONS
Munitions ship, Halifax, Nova Scotia, Dec. 6, 1917, 3.96
SHIP FIRES
Fish-processing vessel, Seattle, Wash., Sept. 16, 1991, 6.48
See also BOAT FIRES
SHOPPING MALL FIRES
New Jersey, 1990, 1.21
New York, May, 1991, 6.77
SMITTLE, WALTER, III
Profile of, 6.20
SMOKE DETECTORS See DETECTORS, SMOKE
SMOKING MATERIALS
Careless disposal of, passenger terminal fire cause, 6.76
Careless disposal of, possible hospital fire cause, 2.27
See also CIGARETTES
SOLVENTS
Gasoline , used as solvent, ignited by gas furnace, 6.28
Ignited by spark from forklift, 4.28
SOUTH CAROLINA
Catastrophic manufacturing plant fire, June 17, 1991, 4.70, 6.80
Manufacturing plant fire, 1991, 3.32
SPAS
National Electrical Code prevents accidents, 4.22
SPONTANEOUS IGNITION
Oil-soaked rags, cause of high-rise fire, 4.71, 5.56, 6.74
SPRINKLER SYSTEMS NOT A FACTOR IN FIRE
Did not cover area of fire, 4.70, 5.30
Inoperable at time of fire, 2.29
Installation incomplete, 4.71, 5.28, 56
SPRINKLER SYSTEMS, SATISFACTORY PERFORMANCE, 1.21, 2.27, 3.34, 4.26, 5.28, 6.25, 22, 23, 26, 27, 28, 29, 30
SPRINKLER SYSTEMS, UNSATISFACTORY PERFORMANCE
Corroded valve prevents operation, 3.32
Overpowered by fire, 6.78, 79
Overpowered by fire, inadequate design, 6.75
Ventilation hood blocks water from fire, 5.25
STAIRWAYS
Catastrophic fire spread up, 4.67, 69
STORAGE FACILITY FIRES
Grain mill and storage facility, Washington, 1991, 4.28
Lumber storage shed, California, 1991, 6.26
Self-storage facility, Massachusetts, 1991, 5.28
See also WAREHOUSE FIRES
STORE FIRES
Clothing, Maryland, 1991, 3.31
Clothing, New Jersey, 1990, 1.21
Clothing, New Jersey, Jan., 1991, 6.78
Department, Minnesota, 1991, 6.25
New York, May, 1991, 6.77
Retail fishing supplies, Washington, 1991, 3.32
STRUCTURAL COLLAPSE
Allows fire spread, 4.71
Fire fighter injuries related to, 1991, 6.61, 62, 64
Hampers fire fighting in warehouse fire, 6.75
STRUCTURAL FIRE SAFETY
Fire hazards of contents, furnishings, and interior finishes, 4.33

T

TANK STORAGE FACILITY FIRES
Colorado, Nov. 25, 1990, 1.60
TANK TRUCK FIRES
Catastrophic, New York, May 20, 1991, 4.72
Michigan, 1991, 6.29
TENNESSEE
Catastrophic dwelling fire, March 9, 1991, 4.67
Hospital fire, 1991, 5.25
TERMINAL FIRES
New York, Sept., 1991, 6.76
TEXAS
Catastrophic aircraft explosion and fire, Sept. 11, 1991, 4.72
Catastrophic dwelling fire, Oct. 7, 1991, 4.68
Catastrophic group home fire, March 24, 1991, 4.70
Fatal laboratory fire, 1991, 5.28
Grass fire, 1991, 2.28
Manufacturing plant fire, June, 1991, 6.79
Manufacturing plant fire, March, 1991, 6.75
Nightclub fire, 1991, 6.25
Refinery fire, April, 1991, 6.75
TORCH
Acetylene, ignites plastic greenhouse cover, 4.25
Ignites hydraulic oil residue, 3.32
Possible cause of oil well explosion and fire, 4.71
TORONTO, CANADA
Hazardous materials response teams, 1.38
TRASH See RUBBISH AND TRASH
TRUCK FIRES
California, 1991, 6.26
Catastrophic, California, Dec. 25, 1991, 4.73
Catastrophic, New York, May 20, 1991, 4.72
Michigan, 1991, 6.29

U

UNITED STATES
Catastrophic fires, 1991, 4.62
Fire fighter fatalities, 1991, 4.40
Fire fighter injuries, 1991, 6.56
Fire losses, 1991, 5.32
Large-loss fires, 1991, 6.40
UTAH
Nursing home fire, 1991, 4.27
Public assembly building fire, 1991, 1.23

V

VACANT BUILDING FIRES
Catastrophic, department store, California, Oct. 22, 1991, 4.71
Michigan, 1991, 2.29
VAGRANTS
Victim of catastrophic fire, 4.69
VAPORS, FLAMMABLE
Pentane vapors ignited by hot plate, 3.33
Solvent vapors ignited by spark from forklift, 4.28
See also GAS FIRES
VEHICLE FIRES
Bus, 4.26
See also AUTOMOBILE FIRES, FORKLIFT FIRES, TRUCK FIRES
VERTICAL OPENINGS See STAIRWAYS
VIRGINIA
Office building fire, 1991, 2.25
VOLUNTEER FIRE SERVICE See VOLUNTEER VIEWS COLUMNS
VOLUNTEER VIEWS COLUMNS
Are professionalism and fun compatible?, 6.22
Importance of NFPA standards to fire service, 3.36
Participatory management enhances morale, 1.96
Reconciling fire fighter safety and customer service needs, 4.86

W

WALLS
Collapse, hamper fire fighting, 6.78
Fire spread within, 6.79
WALLS, FIRE
Lack of, allowed fire spread in sawmill fire, 6.79
WAREHOUSE FIRES
Aircraft parts, Missouri, 1991, 6.26
California, 1991, 1.23
Clothing, Pennsylvania, 2.27
Cold storage, Wisconsin, May, 1991, 6.75
WASHINGTON
Fatal grain mill and storage facility fire, 1991, 4.28
Marina fire, 1990, 1.26
Pyrotechnic accelerants used to ignite series of fires, 6.67
Ship fire, Sept. 16, 1991, 6.48
Store fire, 1990, 3.32
WATER SUPPLY
Inadequate, hampered fire service operations, 2.26, 4.25, 26
WET CHEMICAL EXTINGUISHING SYSTEMS
Nozzles blocked, failed to extinguish fire, 3.34
WILDFIRE MANAGEMENT COLUMNS
NFPA survey identifies wildfire concerns, 1.74
NFPA survey, managers top concerns, 5.96
NFPA survey, national issues, 2.66
WILDLAND FIRES
1991 fire season overview, 1.54
Catastrophic, California, Oct. 20, 1991, 4.72, 6.74
Oregon, Oct., 1991, 6.76
See also WILDFIRE MANAGEMENT COLUMNS
WIND
High, intensifies fire spread, 4.25, 5.25
High, intensifies wildland fire spread, 4.72, 6.74, 76
WINDOWS
Failed, factor in catastrophic fire, 4.67, 68
Furniture blocks access in catastrophic fire, 4.69
WINTERTHUR MUSEUM, DELAWARE
Life safety protection system, 5.63
WIRING, ELECTRICAL
Faulty wiring short circuits, ignites wood framing, 4.68
Ignites joist, 3.34
Malfunctioning or frayed wire ignites fire, 4.67
Short circuit ignites paneling, 2.28
WISCONSIN
Catastrophic drilling rig fire, July 9, 1991, 4.72
Catastrophic dwelling fire, April 22, 1991, 4.68
Catastrophic manufacturing plant fire, May 16, 1991, 4.71
Warehouse fire, May, 1991, 6.75
WOOD FRAMING
Ignited by electric cord, factor in catastrophic fire, 4.67
Ignited by electrical wiring, factor in catastrophic fire, 4.68
WOOD SHINGLES, SHAKES
Produced flaming brands in wildland fire, 4.72
WOOD STOVES
Radiant heat from flue ignites stored wood, 5.25
WYOMING
Fatal dwelling fire, 1991, 5.26
Sawmill fire, 1990, 1.26

Author Index

Babrauskas, Vytenis, 5.45
Bailey, Dan W., 1.74, 2.66, 5.96
Baum, Kevin L., 1.67
Beitel, Jesse, 5.48
Belles, Donald W., 4.32
Birk, David, 3.42
Brunacini, Alan V., 1.18, 2.30, 3.28, 4.30, 5.14, 6.104
Callan, Michael J., 2.22, 3.136, 6.89
Caloggero, John M., 1.72, 3.38
Campbell, David, 6.48
Carter, Harry R., 1.96
Cash, James, 5.63
Connolly, James M., 2.46
Dungan, Kenneth W., 2.32
Dupeire, Walter, 61
Fahy, Rita F., 4.40
Gallagher, Joseph P., 1.42
Granito, John A., 1.47, 90, 2.96, 3.124, 4.96, 6.14
Grant, Casey C., 2.36, 3.96, 5.66
Hall, John R., Jr., 2.4, 3.62, 6.40
Hansen, Bob, 6.48
Henry, Martin F., 1.4, 36
Hunter, Kem, 2.67
Isner, Michael S., 1.60, 3.73, 6.31
Karter, Michael J., Jr., 5.32, 6.56
King, William H., Jr., 4.22
Klein, Burton R., 3.89
Klem, Thomas J., 1.29, 5.56
Koffel, William E., 1.12, 2.14, 3.20, 4.12, 5.22, 6.12
Kosanke, Kenneth L., 6.68
Lathrop, James K., 3.42
Lavelle, Laurie G., 3.80
LeBlanc, Paul R., 4.40, 6.56
Lucas, Lori L., 2.80
Madrzykowski, Dan, 4.34
Mastroianni, August, 3.57, 58, 60
Miller, Alison L., 1.33, 4.62
Miller, George D., 4.4, 5.4, 6.4
Morris, G. Richard, 3.4
Naylor, Honey, 2.55
Ortisi-Best, Richard, 5.65
Powell, Pamela A., 4.76
Russo, Warren P., 6.67
Stittleburg, Philip C., 3.36, 4.86, 6.22
Sullivan, Michael J., 6.40
Summers, Wilford I., 5.12
Taylor, Kenneth T., 6.40
Teague, Paul E., 1.16, 2.20, 41, 3.26, 4.20, 5.20, 50, 68, 6.20
Tokle, Gary O., 1.36
Tremblay, Kenneth J., 1.21, 2.25, 3.31, 4.25, 62, 5.25, 6.25
Van Brunt, Michael W., 3.55
Vink, Marc P., 3.57, 58, 60
Washburn, Arthur E., 4.40
Wilson, Jack S., 1.54

ADVERTISER INDEX

Cerberus Pyrotronics (RSC 001) 7
Chlorine Specialties (RSC 002) 55
Cla-Val Co. (RSC 003) 27
Delta Industries (RSC 004) 85
Edwards Systems Technology (RSC 005) . 66
Facility Management Systems, Inc. 8
FireCom (RSC 007) 88
Fire Control Instrument (RSC 008) 19
Grinnell Fire Protection (RSC 009) 39
HRS Systems (RSC 010) 87
Home Safeguard Industries (RSC 011) 93
Hydronics Engineering (RSC 012) 85
I.E.I. (North America) (RSC 013) 9
IPMA (RSC 014) 94
Macurco, Inc. (RSC 015) 101
Milcor (RSC 016) 18
NFPA 91
Notifier (RSC 018) 1
Potter Electric Signal Co.
(RSC 019, 033) IFC,13
The Protectowire Co., Inc. (RSC 020) 24
R-B Pump (RSC 021) ..... BC
R & G Sloane Mfg., Co., Inc. (RSC 022) ... 37
Ranger Footwear Co. (RSC 023) 23
Rice Hydro Equipment Co. (RSC 024) 94
State Farm Insurance 70–71
System Sensor (RSC 026, 027) 5,53
USG Interiors (RSC 028) 16
Viking Corp. (RSC 029) 30
Walter Kidde Aerospace, Inc. (RSC 030) ... 15
Workrite (RSC 031) ..... IBC
Ziamatic Corp. (RSC 032) 83

NFPA's ADVERTISING ACCEPTANCE GUIDELINES

OBJECTIVES

NFPA solicits and accepts advertising for its publications to fulfill two objectives: 1) for income to support the association's mission; and 2) to impart information to NFPA members and other readers on the availability of products, systems, and services.

CONDITIONS OF ACCEPTANCE

In general, NFPA uses the following criteria in deciding which advertisements to accept for its publications, but reserves the right to reject any advertising for any reason whatsoever. All accepted advertising is subject to the conditions listed.

1. NFPA will not accept advertising when it finds any reason to believe that the advertised product, system, or service does not conform to NFPA policies as stated in its codes and standards.

2. NFPA will not accept advertising when it finds any reason to believe that the advertised product, system, or service constitutes a fire or related hazard.

3. NFPA will not accept advertising that deals with disputed technical issues relating to its codes and standards; this applies to previously adopted standards and to standards being considered for adoption by NFPA.

4. NFPA will not accept advertising unless the advertiser is prepared to validate any claims made in the advertisement about the product, system, or service being advertised.

5. NFPA will not accept advertising that contains derogatory comments about the advertiser's competitors or about the competitors' products or organizations.

6. The advertiser understands that an advertisement in an NFPA publication does not constitute, nor shall it be interpreted as constituting, an endorsement by NFPA of the advertiser or of the advertiser's organization, product, system, or service.

7. The advertiser understands that the fact of advertising in an NFPA publication is not to be used to market or promote the advertiser or the advertiser's organization, product, system, or service.

8. The advertiser understands that NFPA's name and image are not to be used in any commercial activities in any manner that would indicate, either directly or indirectly, NFPA's endorsement of the advertiser or of the advertiser's organization, product, system, or service.

9. NFPA will not accept advertising that is discriminatory because of race, religion, color, national origin, sex, age, or physical handicap.

WHAT'S YOUR SECOND WAY OUT OF THE ROOM YOU'RE IN?



WAYOUT 1



WAYOUT 2

How would you escape if there were a fire? What if that escape route were blocked?

You should plan "two ways out." And you should plan them now—before there's a fire.

Have a family escape drill at home tonight.

LEARN NOT TO BURN.

National Fire Protection Association